

METERING TIPS

The following chart is to be used as a guide.
The size of the orifice is given in thousandths of an inch or by drill bit size.

	Brown	(.006)		Medium Green	(68)
	Clear	(.008)		Clear Pink	(66)
	Bright Purple	(80)		Yellow Green	(64)
	White	(79)		Burgandy	(62)
	Pink	(78)		Pale Pink	(60)
	Corn Yellow	(77)		Light Blue	(58)
	Dark Green	(76)		Dark Purple	(56)
	Orange	(74)		Navy Blue	(54)
	Gray	(72)		Clear Aqua	(53)
	Light Green	(70)		Black	(52)

Orifice hex head 7/32''
Threads 8-32

The number under each color in the chart below represents the
average ounces of water-thin chemical which will pass through the tip per minute.

METERING TIP SELECTION IN OUNCES PER MINUTE (AVERAGE)

COLOR	Brown	Clear	Bright Purple	White	Pink	Corn Yellow	Dark Green	Orange	Gray	Light Green	Medium Green	Clear Pink	Yellow Green	Burgandy	Pale Pink	Light Blue	Dark Purple	Navy Blue	Clear Aqua	Black
Thin Chemical	0.84	1.16	1.4	2.0	2.7	3.4	4.0	5.3	6.1	7.0	8.5	9.2	11.2	12.5	12.9	14.2	17.6	21.4	30.2	40.4